

March 20, 1985

Potential Hazardous Waste Site - Site Inspection Report

James L. Graham, Jr., P.E.  
Chief, Public Water Supply Section (6W-SP)

Gerald Fontenot  
Chief, Field Response Section (6ES-EF)

In response to the CERCLA investigation reports which you recently sent to the Water Supply Branch, I am attaching our comments. Thank you for the opportunity to review these documents.

Attachments: Review Sheet on:

1. Garland Co. Sanitary Landfill
2. Old CHEMFAB Dump
3. Piper Industries
4. Mike Greogory Property
5. Arco Drumright Gasoline Plant
6. Total Petroleum Comp. OK 1589
7. Western Co. of North America

FIT TASKED 1/24/85 sampling

cc: Martha McKee  
George Buynoski

— this received long after FIT tasked —  
Inspection ongoing per FIT mo. Report.

OKD057705972

SUPERFUND FILE

OCT 21 1992

REORGANIZED